

TEMPERATURE ACCESSORIES

Do-It-Yourself Sensor Kit

Model SK-2

All materials, tools and instructions for making interchangeable Type T (copper-constantan) thermocouple sensors.

Contents:

- 50 feet TW-30 wire
- 50 feet TW-26 wire
- 10 type T miniature thermocouple plugs
- Epoxy
- Miniature soldering iron
- Wire cutters & strippers
- Xacto® Knife
- 3X Loupe
- Tweezers
- Instruction Manual



SK-2 , Sensor Kit

Extension Leads, Plugs & Sockets

EXT-6 - 6 ft. probe extension lead plugs into thermometer. Socket on other end accepts any type T probe.

TP-10 - Thermocouple Plug Kit. 10 copper-constantan plugs, epoxy, washers, instructions

TS-10 - Thermocouple Socket Kit. 10 copper/constantan sockets, epoxy, washers, instructions.

For Type T Thermocouple Wire see page 9

For Type T Thermocouple probes see pages 6-7

Thermocouple Selector Switches



SBT-5, SWT-5 (background), foreground SWT-2 Thermocouple Selectors



Model SWT-2 Lets you use two probes in a thermometer which has a single input. SWT-2 was designed with the BAT-12 in mind - it is small and easy to carry in the field with the portable BAT-12 - but it also fits any miniature Type T socket.

Thermometer Stand

Model TTS-4

Table top tripod with adjustable viewing angle. For use with TH-5, TH-8 and BAT-12 thermometers.

